

# Work Permit # DRL-2010-15 Work Order # \_\_\_\_ Job# \_\_\_\_ Activity# \_\_\_\_

ork requester fills out this section.		ding Work Permit		-				
Requester: Don Lynch	Date: 07/20/2010	Ext.: 2253						
Other Contact person (if different fro	om requester): Carter Biggs		Ext.: 7515					
Work Control Coordinator: Don Lynd	ch	Start Date: 07/21/2010	Start Date: 07/21/2010 Est. End Date: 11/1/2010					
trief Description of Work: PHENIX Drift Chamber (DC) East & West Electronics Troubleshooting and Repairs								
uilding: 1008	Room: IR	Equipment: DC East & W	est Service Provider: PH	ENIX techs & PC experts				
, Requester/Designee, Service Pr	rovider, and ES&H (as necessary)	fill out this section or attach an	alysis					
ES&H ANALYSIS								
Radiation Concerns	None ☐ Activation	Airborne	☐ Contamination	Radiation				
Radiation Generating Devices:	Radiography	☐Moisture Density Gauges	☐Soil Density Gauges					
☐ Special nuclear materials invo	lved, notify Isotope Special Materia	ls Group	Fissionable materials inv	olved, notify Laboratory Criticality Officer				
Safety Concerns	■ None	☐ Ergonomics	•					
☐ Adding/Removing Walls or Ro	Confined Space*	☐ Explosives	☐ Lead*	☐ Penetrating Fire Walls				
Adding/Removing waits of Ro	Corrosive	☐ Flammable		☐ Pressurized Systems				
☐ Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*		☐ Rigging/Critical Lift				
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*				
☐ Biohazard*		☐ Hydraulic	□ Non-ionizing Radiation*	☐ Vacuum				
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*	Other				
* Does this work require medical cl	learance or surveillance from the O	ccupational Medicine Clinic? 🔲 🗅	∕es 🔀 No					
Environmental Concerns		None     Non	☐ Work impacts Environme	ental Permit No.				
☐ Atmospheric Discharges (rad/r	non-rad)	☐ Land Use	Soil	☐ Waste-Mixed				
<u> </u>	<u> </u>		Activation/contamination					
☐ Chemical or Rad Material Stor	rage or Use	Liquid Discharges	☐ Waste-Clean	☐ Waste-Radioactive				
Cesspools (UIC)		Oil/PCB Management	☐ Waste-Hazardous					
☐ High water/power consumption	n	Spill potential	☐ Waste-Industrial	Underground Duct/Piping				
Waste disposition by:	II .	☐ Spill potential	☐ Waste-Illuustilai	Other				
Pollution Prevention (P2)/Waste	Minimization Opportunity:	None ☐ Yes		Other				
FACILITY CONCERNS	None None	Notic 1 162						
FACILITY CONCERNS	☐ Electrical Noise	☐ Potential to Cause a	Ealco Alarm	☐ Vibrations				
☐ Access/Egress Limitations			Temperature Change	Other				
☐ Configuration Control	☐ Impacts Facility Use Agreer Configuration Control ☐ Maintenance Work on Venti		Utility Interruptions	☐ Other				
WORK CONTROLS	I Waintenance Work	on ventilation systems	Othity interruptions					
Work Practices								
None	☐ Exhaust Ventilation		Spill Containment	Security (see Instruction Sheet)				
		Posting/Warning	<u> </u>					
Back-up Person/Watch	☐ HP Coverage	Signs	☐ Time Limitation	☐ Other				
Barricades	☐ IH Survey	☐ Scaffolding-requires	Iding-requires Warning Alarm (i.e. "high level")					
	☐ In Survey	inspection	warning Alarm (i.e. nigr	1 level )				
Protective Equipment								
None	☐ Ear Plugs	Gloves	☐ Lab Coat					
☐ Coveralls	☐ Ear Muffs	Goggles	Respirator	☐ Safety Harness				
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	Safety Other				
				Shoes				
Permits Required (Permits must b		I leave air Fire Ducto etic	a Contant					
None	Cutting/Welding	Impair Fire Protection	·					
Concrete/Masonry Penetration	_ 55 5		P No					
Confined Space Entry	☐ Electrical Working H	Hot Other						
Dosimetry/Monitoring			T 🗆 =: 5					
None     Non	Heat Stress Monitor		☐ TLD					
☐ Air Effluent	☐ Noise Survey/Dosin	meter Self-reading Pencil Dosimeter	☐ Waste Characterization					
	□ 0 /0 · · · l · · · ("b) · 0 ·	Colf reading Digital	Class Observed COde at a factor of					
☐ Ground Water ☐ O <sub>2</sub> /Combustible Gas		Dosimeter Dosimeter	Other Check O2 level prior to entry					
☐ Liquid Effluent	uid Effluent Passive Vapor Monitor							
		Pump						
Training Requirements (List below								
Confined Space, CA –Collider User, PHENIX Awareness, Working at Heights (Fall Protection)								
Based on analysis above, the Waratings below:	alkdown Team determines the ris	sk, complexity, and coordination		I hazard ratings are low, only the following lowed, there is no need to use back of				
ES&H Risk Level:		erate  High	WCC:	Date:				
Complexity Level:		erate  High	Service Provider:	Date:				
Work Coordination:		erate  High	Authorization to start	Date:				
			(Departmental Sup/WCC/De					

	Work Plan (procedures, timing, equipment, and personnel availability need to be addressed): See Attached Work Plan											
	Special Working Conditions Required: None											
	Operational Limits Imposed: Modification work limited to lower octants easily reachable when standing on lower magnet superstructure.											
	Post Work Testing Required: No											
	Job Safety Analysis Required: ☐ Yes		Walkdown Required: ☑ Yes ☐ No									
	·											
	Reviewed by: Primary Reviewer will determine the size of the review team and the other signatures required based on hazards and job complexity. Primary Reviewer signature meathat the hazards and risks that could impact ES&H have been identified and will be controlled according to BNL requirements.											
	<u>Title</u>			rint) Signature		Life #		<u>Date</u>				
	Primary Reviewer											
	ES&H Professional											
	Other											
	Other											
	Work Control Coordinator											
	Service Provider											
		Review	v Done: in series	☐ team								
ļ		TOVION	Pone.   In series	Liteam								
4. Joh	site personnel fill out this section.											
	Note: Signature indicates personnel performing work have read and understand the hazards and permit requirements (including any attachments).											
	bb Supervisor:				Contractor Supervisor:							
	Workers:		Life#:		Workers: Life		Life#:	#:				
	Workers are encouraged to provide feed	lback on I	ES&H concerns or on idea	as for improved job	work flow. Use f	eedback form or space be	low.					
5. De	partmental Job Supervisor, Work Contr	ol Coord	inator/Designee									
	Conditions are appropriate to start work:			controls are in plac	ce and site is read	ly for job.)						
	Name:	Name: Signature:			Life#:			Date:				
6. Dei	partmental Job Supervisor, Work Requ	ester/Des	signee determines if Pos	t Job Review is r	eauired. Nes	s 🗆 No						
	Post Job Review (Fill in names of review		- <del>J</del>									
	Name:	ame: Signature:			Life#:		Date:					
	Name: Signature:		Life#:		Date:		:					
I												
7. Wo	rker provides feedback. Worker Feedback (use attached sheets	as nacas	ean/l									
	Worker Feedback (use attached sheets as necessary) a) WCM/WCC: Is any feedback required? ☐ Yes ☐ No											
	b) Workers: Are there better methods or safer ways to perform this job in the future?   Yes   No											
8. Clo	8. Closeout: Work Control Coordinator (authorizing dept.) checks quality of completed permit and ensures the work site is left in an acceptable condition. (WCC can delegate											
	up of work area to work supervisor)	<u> </u>	Γ				1	,				
	Name:		Signature:		Life#:		Date:					
	Comments:											

DC East and West Electronics Repairs in the PHENIX Experimental Hall (bldg. 1008).

### Introduction

During the 2010 RHIC Shutdown, the PHENIX Drift Chamber (DC) group will use the opportunity afforded by the temporary relocation of the PHENIX Central Magnet (CM) to access and repair DC West electronics modules. These modules would otherwise be practically inaccessible.

All work to be done involves worker planned work including accessing troubleshooting removal, repair, test and replacement of electronics modules. Troubleshooting and testing will be performed in accordance with limits of BNL, CAD and PHENIX policy in accordance with PHENIX Awareness training.

The access will be accomplished with some combination of suitable manlift(s) (To Be Determined), standard scaffolding and or custom designed work platforms. The method(s) of access employed will be determined in consultation with the PHENIX CAD liaison engineer and shall comply with all applicable BNL, CAD and PHENIX use and training policies.

Note: The DC group may perform similar work on the DC East during the same time, if deemed necessary and appropriate by the PHENIX DC group.

#### Task Schedule:

Step 0. ¼ day General planning meeting

Step 1. 3 days
Start with DAQ running and HV "in hands"
Start gas flow 2.5-3 days
Dissemble electronics, installation of dummy grounds
Transportation boards to SBU, start board testing

# Step 2.

Work on HV cards and HV problems, 2-3 days Cut the mylar window for wire removal, 1-2 days Final test with HV Work on electronics and its test at SBU - 5-7 days

## Step 3.

Start signal board and ASD/TMC boards mounting after HV work finished. 2-3 days

## Step 4.

Final electronics assembling and testing. 3-5 days

#### Additional Notes:

- 1) DAQ and one person from ONCS group are needed to help with standalone tests, HV server must be working.
- 2) Order thermo pads and grease for chip cooling on amplifier/TMC boards prior to commencement of these tasks
- 3) Argon and CO2 70/30 shall be supplied to the detector. Number of CO2 bottles shall be calculated from the following:

DC volume is  $\sim$ 3500 liters, the mixture will be 70% Ar + 30% CO2. For the first flash to get working mixture at least 4-5 volumes are needed at the beginning, then about one volume per day for approximately 10 days for all HV tests. [52,500 liters gas, minimum] PHENIX gas experts shall determine bottle size and quantity to provide this volume plus a reasonable safety margin.

- 4) Gas flow meters and some plastic piping as necessary.
- 5) DO NOT PREPARE GROUNDING CONNECTORS in advance, north and south sides are different for cable orientation! Grounding connectors shall be prepared as needed.
- 7) DC experts shall determine and acquire appropriate tools for electronics disassembly.